



## Tecvac Makes Problems Go Away - Bug Holes

### PROBLEM

- Precast column members displayed severe "bug holes" in the delivered product.
- Numerous attempts by others could not achieve acceptable finish.
- If the desired finish could not be achieved, the member would be rejected.

### SOLUTION

- The failed materials were removed from the members
- Polymer modified grout was colored to match the member
- The member was prepared and scrubbed with the color matching repair material and allowed to cure.
- High pressure water was applied to the repaired area and examined for damage and scour.

